

..... 1  
..... 1



```
Shell
RUNTIME> runcount
    RunCount = 1

RUNTIME> runcount(10)
    RunCount : 1 → 10

RUNTIME> ecmSxSt_GetMotState(0,0,ref error)
    Run Count : 10,
    ElapsedTime : 91 (us)
```

```
RUNTIME> runcount
RUNTIME> runcount(10)
```

- RunCount :
- RunCount(10) :            10
- exit : RunTime Mode            Normal Mode

× PC , Core, Task, Thread 가 .

From:  
<http://comizoa.com/info/> - -

Permanent link:  
[http://comizoa.com/info/doku.php?id=application:comiide:tool:shell:shell\\_runtime\\_mode&rev=1543285695](http://comizoa.com/info/doku.php?id=application:comiide:tool:shell:shell_runtime_mode&rev=1543285695)

Last update: **2024/07/08 18:23**