


가 1
가 2

ETS-DO

X

가



'ON'


'OFF'

- No.1 OFF :
 - ETS-DO16 : Ch.0 ~ Ch.7
 - ETS-DO32 : Ch.16 ~ Ch.31
- No.1 ON :
 - ETS-DO16 : Ch.0 ~ Ch.7
 - ETS-DO32 : Ch.16 ~ Ch.31
- No.2 OFF :
 - ETS-DO16 : Ch.8 ~ Ch.15
 - ETS-DO32 : Ch.0 ~ Ch.15
- No.2 ON :
 - ETS-DO16 : Ch.8 ~ Ch.15
 - ETS-DO32 : Ch.0 ~ Ch.15

가

- ComiIDE 1.5.1.3 , ESI
 - **COMIZOA-ETS**
 - , “COMIZOA_ETS.xml” ..\ComiIDE\Data\XML“

- **Slaves EEPROM Update**

• 1) **Update**

- 2)

- 3) **Load**

Module List



- COMIZOA → **ETS-DO16N-E-LD** , Select

Slave RW

[02FF] MASTER-DC 1

Info EEPROM CoE SDO Register 2

EtherCAT

- Net 0
 - 00 : [02FF] MASTER-DC
 - 01 : [020B] ETS-DO16N-E


3

No	Register	Value	Current
0x0	PDI Control	0x0504	0x0504
0x1	PDI Configuration	0x0E00	0x0E00
0x2	Pulse length Sync signals	0x2710	0x2710
0x3	Extended PDI Configuration	0x0000	0x0000
0x8	Vendor ID	0xAAAAAA...	0x05132AA00
0xA	Product Code	0x5132AA00	0x5132AA00
0xC	Revision No	0x14111001	0x14111001

- **Update**

- **Slaves**

EEPROM Update




- 1) **Update**

- 2)

- 3) **Load**

Module List



- COMIZOA → **ETS-DO16N-E** , Select

Slave RW

[02FF] MASTER-DC

Info EEPROM CoE SDO Register Update

EtherCAT

- Net 0
 - 00 : [02FF] MASTER-DC
 - 01 : [020B] ETS-DO16N-E

Load Read Update

No	Register	Value	Current
0x0	PDI Control	0x0504	0x0504
0x1	PDI Configuration	0xE000	0xE000
0x2	Pulse length Sync signals	0x2710	0x2710
0x3	Extended PDI Configuration	0x0000	0x0000
0x8	Vendor ID	0xAAAAAA...	0xAAAAAA...
0xA	Product Code	0x5132AA00	0x5132AA00
0xC	Revision No	0x14111001	0x14111001

Index Order ID Order

- **Update**

X

'-LD' 'Latch Disable'

'-LD' 가 EEPROM Update

×

Warning!

From:

<http://comizoa.com/info/> - -

Permanent link:

http://comizoa.com/info/doku.php?id=faq:io:ethercat:01_ets_do2&rev=1623045707

Last update: **2024/07/08 18:22**