

Case 1 ..... 1  
Cause ..... 1  
Add Info ..... 1  
Solution ..... 1

ethercat, , panasonic, , , 80.6, alarm, error, noise, jitter, lostframe

# PANASONIC : Alarm 80.6

x 80.6 .

## Case 1

### Cause

- SyncMode 가 SM2 Event Mode , Jitter LostFrame

### Add Info

- ?
- PLL (Phase-Locked Loop) :
- PLL
  - 가 ( )
  - Driver IRQ Source( ) 가

### Solution

- SyncMode 가 SM2 Event Mode , DC Sync Mode

From: <http://comizoa.com/info/> - -

Permanent link: [http://comizoa.com/info/doku.php?id=platform:ethercat:70\\_users\\_guide:20\\_ts:panasonic\\_alarm\\_80.6&rev=1560402132](http://comizoa.com/info/doku.php?id=platform:ethercat:70_users_guide:20_ts:panasonic_alarm_80.6&rev=1560402132)

Last update: 2024/07/08 18:22