

10	1
16	2

10 & 16

× 10 / 16

10

Category

All

10 16

Load All
 Save All
 Compare To File
 Read All
 Write 1:N
 Write N:N
 EEP All

Load One
 Save One
 Compare To Axis
 Read One
 Write One
 EEP One


Item	Name	Minimum	Maximum	Defalut	Servo	Value	Unit
<input type="checkbox"/>	0	0	1	1	1	1	---
<input type="checkbox"/>	1	0	6	0	0	0	---
<input type="checkbox"/>	2	0	6	1	1	1	---
<input type="checkbox"/>	3	0	31	13	14	14	---
<input type="checkbox"/>	4	0	10000	250	25	25	1%
<input type="checkbox"/>	8	0	1048576	0	10000	10000	---
<input type="checkbox"/>	9	0	1073741824	1	1	1	---
<input type="checkbox"/>	10	1	1073741824	1	1	1	---
<input type="checkbox"/>	11	1	262144	2500	2500	2500	1 Pulse/r
<input type="checkbox"/>	12	0	3	0	0	0	---

- 10

Minimum / Maximum / Default / Servo / Value

10

0	10000	250	25	25	1%
0	1048576	0	10000	10000	---
0	1073741824	1	1	1	
1	1073741824	1	1	1	
1	262144	2500	2500	2500	
0	3	0	0	0	
0	500	500	300	300	
0	134217728	100000	10000	10000	
0	2	1	1	1	
0	3	3	3	3	
0	4	0	0	0	
0	30000	480	630	630	
1	32767	270	350	350	
1	10000	210	160	160	
0	5	0	0	0	



- Cell 10 Keypad가 .
- H 16 Keypad 가 , 0x2710 16 , 10
- 10 Keypad "0x2710" . 10 16 Keypad 2710 0x2710 16

16

Category

All

10 16

Load All Save All Compare To File Read All Write 1:N Write N:N EEP All

Load One Save One Compare To Axis Read One Write One EEP One

Item	Name	Minimum	Maximum	Default	Servo	Value	Unit
0	제조사 사용	0x00	0x01	0x01	0x01	0x01	---
1	제어 모드 설정	0x00	0x06	0x00	0x00	0x00	---
2	실시간 오토튜닝 설정	0x00	0x06	0x01	0x01	0x01	---
3	실시간 오토튜닝 기계 강성 설정	0x00	0x1F	0x0D	0x0E	0x0E	---
4	관성비	0x00	0x2710	0xFA	0x19	0x19	1%
8	제조사 사용	0x0000	0x100000	0x0000	0x2710	0x2710	---
9	제조사 사용	0x0000	0x40000000	0x0001	0x0001	0x0001	---
10	제조사 사용	0x0001	0x40000000	0x0001	0x0001	0x0001	---
11	지원 없음(모터 1회전당 출력 펄스 수)	0x0001	0x40000	0x09C4	0x09C4	0x09C4	1 Pulse/r
12	지원 없음(펄스 출력 논리 반전)	0x00	0x03	0x00	0x00	0x00	---

• 16 Minimum / Maximum / Default / Servo / Value 16

0x00	0x2710	0xFA	0x19	0x19	1%
0x0000	0x100000	0x0000	0x2710	0x2710	
0x0000	0x40000000	0x0001	0x0001	0x0001	
0x0001	0x40000000	0x0001	0x0001	0x0001	
0x0001	0x40000	0x09C4	0x09C4	0x09C4	
0x00	0x03	0x00	0x00	0x00	

KeyPad

0x2710

<< >> +/-

1 2 3 OK

4 5 6

7 8 9 Exit

H 0 .

A B C Dec

D E F Hex

- Cell 16 KeyPad가 , 10 KeyPad 10000 10
- Dec 10 KeyPad , 16
- 16 KeyPad 2710 10 16
- 16 KeyPad 2710 0x2710

From:

<http://comizoa.com/info/> - -

Permanent link:

http://comizoa.com/info/doku.php?id=application:comiide:tool:servotunes:40_hexa&rev=1542209571

Last update: **2024/07/08 18:23**