

Case 1 1
 AddInfo 1
 Cause 1
 Solution 1

[ethercat](#), [homing](#), [-21072](#), [touchprobe](#),

ErrorCode : -21086

× -21086 Error

Case 1

AddInfo

- Homing Method 101 -21086 Error

Cause

- Touch Probe

Solution

- TouchProbe Homing Method

From:
<http://comizoa.com/info/> - -

Permanent link:
http://comizoa.com/info/doku.php?id=platform:ethercat:100_api:5_errorcode:21086&rev=1560402286

Last update: **2024/07/08 18:22**