

Table of Contents

| | |
|---------------------|---|
| Case 1 | 1 |
| Solution | 1 |

LS MECAPION : SafeOP 전환 실패

× LS MECAPION Driver 연결 시 PreOP → SafeOP 전환이 안됨.

Case 1

check Cause



- XML ¹⁾에서 SM2, SM3의 Enable="0"으로 되어 있음

Solution

- Enable="1"로 변경

¹⁾

LS Mecapion L7N_V0.03e.xml

From:

<http://comizoa.com/info/> - -

Permanent link:

http://comizoa.com/info/doku.php?id=platform:ethernet:70_users_guide:20_ts:ls_safeop_failed&rev=1540444146

Last update: **2024/07/08 18:22**